

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 145

Dated: 07/03/2024

It is certified that the existing building **Queens' College, CBSE New Generation School, at Limbodi, Khandwa Road, Indore, MP 452 020**, is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor First Floor Second Floor	Ground Floor First Floor Second Floor	-	-	-	-

The building is owned/occupied by **Queens' College, Indore** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Works Dept, District Sub division No.1, Indore** on **05/03/2024** in the presence of **Mrs. Geetha Somasekharan, Principal, Queens' College, Indore** and that the building/premises is fit for occupancy for running school with effect from Nursery to Class XII for a period of **One year** in accordance with rule and subject to compliance of the specific conditions as appended.

1. **Building is structurally Sound and Safe**
- 2.
- 3.
- 4.

Issued on **07/03/2024** at **03:00 pm** by **Sub Divisional Officer PWD, Dist. Sub Division No. 1, Indore.**

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : \_\_\_\_\_

Name : **Sub Divisional Officer**

Designation : **P.W.D. (B&R) Dist. Sub Dn. No. 1, INDORE**

Name & Address of Department/ Office:  
Sub Divisional Officer  
PWD, District Sub Division No. 1  
Indore.